

4-10-91

Clément

STAFF	POLICY NUMBER									
04	1	2	8	3	4	3	9	5	7	
SALN						DATE OF LOSS				
						3 36 91				

Car Location

NAME OF REPAIR SHOP (Agrees to complete and guarantee repairs listed below)		ADDRESS NO.		STREET		CITY		SHOP PHONE NO.	
YEAR 1968		MAKE AND MODEL FORD T-BIRD		4-C TURBO		IDENTIFICATION 1E4004T310001X		LICENSE NO. FWR 264	
Repair		Revised						SPEEDOMETER 32589	

Item	Quantity	DESCRIPTION OF REPAIRS	LABOR	PARTS	SUBLET
✓	1	HOOP	1.8	260 ⁰⁰	-
✓	1	LT FENDER	3.5	-	-
✓	1	RT " "	4.5	-	-
✓	1	W/S UPPR PUL MOLD	.7	245 ⁰⁰	-
✓	1	RT DOOR	3.5	-	-
✓	1	LT DOOR	1.5	238 ⁰⁰	-
✓	1	DOOR	2.5	-	-
✓	1	ROOF	1.5	238 ⁰⁰	-
✓	1	LT 1/4	22.0	553 ⁰⁰	-
✓	1	RT 1/4	6.0	-	-
✓	1	DECK LTR	4.5	-	-
✓	1	RT DOOR RR PILLAR MOLD	1.0	245 ⁰⁰	-
✓	1	LT " " " "	.4	208 ⁰⁰	-
✓	1	2-STAGE	1.4	208 ⁰⁰	-
✓	1	REFINISH COMPLETE	4.5	-	-
✓	1	STRIPES	27.0	-	504 ⁰⁰
			-	-	2 ⁰⁰

Sub Total 415
Paul Hulsebach
Inspector

☐ National Accounts Supplement

56460
345726
6000
368726

4-10-91
Date Inspected

REPAIR SHOP: Any supplementary repairs required must be inspected before repair.